



## **Spinchron DLX Tach Sensor Cable Routing**

The tach sensor cable is very sensitive to noise—if it is routed too close to the motor harness or brake resistor it can generate Error 41 during deceleration.

Before installing a Spinchron DLX replacement motor (365434), ensure that the tach sensor cable is detached from the motor harness. Route the tach sensor cable away from the brake resistor.